

Abrasive Bristle Brushes

Safety



Flap wheels perform best between 15-20m/s, this giving the optimum balance between stock removal, surface finish, cutting temperature and wheel life.

NB! Excess speed is dangerous and may result in wheel disintegration, flaps pulling out, grain shedding and overheating.

NEVER USE FLAP WHEELS AT SPEEDS IN EXCESS OF 40m/s!

Do not use wet or in any coolant or oil. Flap wheels are direction sensitive.

Use in accordance to ANSI B7.1.

Abrasive Bristle brushes are use for med and light cleaning and deburing, in applications where excessive stock removal needs to be avoided. Good for imperfect surfaces and hard to reach spaces.

Available in a range of sizes, grit sizes, grain types and bristle thicknesses.

