

## Mounted Points



### Safety




Mounted Points perform best between 350-600m/min, this giving the optimum balance between stock removal, surface finish, cutting temperature.

**NB! Excess speed is dangerous and may result in chipping and breaking  
NEVER USE Mounted Points AT SPEEDS IN EXCESS of 600m/min!**

Use in accordance to ANSI B7.1.



## A-Shape Mounted Points



## W-Shape Mounted Points

