

Mounted Points



Safety




Mounted Points perform best between 30-50m/s, this giving the optimum balance between stock removal, surface finish, cutting temperature.

**NB! Excess speed is dangerous and may result in chipping and breaking
NEVER USE Mounted Points AT SPEEDS IN EXCESS of 50m/s!**

Use in accordance to ANSI B7.1.



A-Shape Mounted Points



W-Shape Mounted Points

